

INTERNAL SERVICE BULLETIN (DEFECTS).

No. 50010.

17th. January, 1949.

UNIT AFFECTED.

PETROL TANKS.

SUBJECT.

Inclination to rust.

MODELS.

Land-Rover.

CAUSE.

Porosity of rust-proof plating.

Petrol tanks on Land-Rovers have been going out unpainted and although they are manufactured in terne-coated steel, still incline to rust.

ACTION TAKEN.

On production in future, the tanks will be painted with black, petrol resisting, paint.

Vehicles that already have the petrol tanks fitted about the works, are being painted with aluminium paint, as this is the only method which will not show a patchy effect, being the same colour as the petrol tank.

ACTION TO BE TAKEN.

Any complaints from outside, should be dealt with by advising or supplying the aluminium paint; the painting to be carried out by our agents. All vehicles passing through Service, should be dealt with as found necessary.

\*\*\*\*\*