

Issue 1

Date 1.1.52

Sheet 1 of 1 Sheet

MODELS AFFECTED

1952 Land-Rover

UNIT AFFECTED

ENGINE

IGNITION TIMING

Contrary to information contained in the current editions of the Land-Rover Operation Manual and Workshop Manual, ignition timing on all 1952 Land-Rovers (and earlier vehicles fitted with 2-litre engines) should be set at 8° B.T.D.C. and not 15° B.T.D.C. as stated. There is a timing mark at 8° already marked on the flywheel.

This information should be brought to the notice of all service and sales personnel and fleet operators immediately; private owners should be informed as necessary at the first opportunity.