

Bulletin Number 5041	Issue 1	Date 16.2.49	Sheet 1 of 2 Sheets
----------------------	---------	--------------	---------------------

<b>MODELS AFFECTED</b> 1948-49 "60" AND "75" LAND-ROVER	<b>UNIT AFFECTED</b> <h2 style="text-align: center;">ENGINE</h2>
---	---

**COMPLAINT**

**SUBJECT**  

## PARTS REQUIRED FOR DECARBONISING

As a result of several requests from agents, this Bulletin details parts which we recommend for renewal when the engine is decarbonised.

Model "60" (Engines numbered 8210001 onwards).

Description	Quantity	Part No.
Cylinder head gasket	1	212322 or 217511
Joint washer for exhaust manifold	2	09184
Joint washer for inlet manifold	2	09179
Joint washer for water branch	1	210447
Joint washer for top rocker cover	1	212283
Joint washer for side rocker cover	1	213235
Sealing washer (inner) for top breather pipe	1	212173
Sealing washer (outer) for top breather pipe	1	216709
Joint washer for oil pipe	2	210640
Sealing ring for inlet valve	4	210517
Joint ring between water pump and thermostat housing	1	09170
Joint washer for exhaust pipe (RHD)	1	213358
or Joint washer for exhaust pipe (LHD)	1	216138
Joint washer for carburettor	2	212233
Packing for carburettor	1	212232
Sealing ring for sparking plug cover	4	213172

Model "75" (Engines numbered 8410001 onwards)

Description	Quantity	Part No.
Cylinder head gasket	1	212324
Joint washer (outer) for exhaust manifold	2	09184
Joint washer (centre) for exhaust manifold	1	210508
Joint washer for top rocker cover	1	212284
Joint washer for side rocker cover	1	213236
Sealing washer (inner) for top breather pipe	1	212173
Sealing washer (outer) for top breather pipe	1	216709
Joint washer for oil pipe	2	210640
Sealing ring for inlet valve	6	210517
Joint ring between water pump and thermostat housing	1	09170
Joint washer for exhaust pipe (RHD)	1	213358
or Joint washer for exhaust pipe (LHD)	1	216138
Joint washer for inlet manifold	3	09179
Joint washer for water branch	2	210598
Joint washer for carburettor	2	213939
Packing for carburettor	1	212620
Sealing ring for sparking plug cover	6	213172

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.

**THE ROVER CO. LTD.,**  
**SOLIHULL, BIRMINGHAM, ENGLAND.**

**SERVICE BULLETIN**

Bulletin  
 Number 5041

Issue 1

Date 16.2.49

Sheet 2 of 2 Sheets

**MODELS AFFECTED**

1948-49 "60" AND "75"  
 LAND-ROVER

**UNIT AFFECTED**

**ENGINE**

**COMPLAINT**

**SUBJECT**

**PARTS REQUIRED FOR DECARBONISING**

LAND-ROVER (Engines numbered 860001 onwards)

Description	Quantity	Part No.
Cylinder head gasket	1	212322
Joint washer for exhaust manifold	2	09184
Joint washer for inlet manifold	2	09179
Joint washer for water branch	1	210447
Joint washer for top rocker cover	1	212283
Joint washer for side rocker cover	1	213235
Sealing washer (inner) for top breather pipe	1	212173
Sealing washer (outer) for top breather pipe	1	216709
Joint washer for oil pipe	2	210640
Sealing ring for inlet valve	4	210517
Joint washer between water pump and thermostat housing	1	09170
Joint washer for exhaust pipe (RHD)	1	213358
or Joint washer for exhaust pipe (LHD)	1	216138
Joint washer for carburettor	2	212233
Packing for carburettor	1	212232
Sealing ring for sparking plug cover	4	213172

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.