

Bulletin  
Number 5051

Issue 1

Date 30.6.49

Sheet 1 of 1 Sheet

MODELS AFFECTED

LAND-ROVER

UNIT AFFECTED

WINDSCREEN

COMPLAINT

SUBJECT

## FITTING WINDSCREEN VENTILATOR

A full-width ventilator panel has been designed for fitting across the bottom of the Land-Rover windscreen in place of the standard plain panel. It will be offered as an item of extra equipment for all vehicles despatched in the future and is also available from our Spares Department for fitting to vehicles already in service. This ventilator serves two main purposes:—

- (i) The air stream so created greatly reduces the amount of dust carried into the rear of the vehicle by eddy currents.
- (ii) In hot weather it provides a cooling stream of air for driver and passengers.

The panel is therefore a desirable fitment when the vehicle is largely operated under hot and/or dusty conditions.

The complete kit for fitting this ventilator is supplied under Part No. 232974. *3-0-0*

Proceed as follows:—

1. Remove the plain panel from the windscreen by shearing off the retaining rivets and removing the drive screws securing it to the mid screen rail. Also remove the two lower drive screws securing the vertical screen glass frames to this rail.
2. Remove the split pins and joint pins securing the windscreen fasteners to the windscreen lower rail.
3. Fit the new panel complete to the windscreen with its upper edge under the screen glass frame and secure it with the drive screws removed with the original panel. Replace the two drive screws securing the vertical frame to the mid rail.
4. Secure the ventilator hinge arms to the windscreen fasteners, using the new joint pins and split pins supplied.
5. The panel can now be secured in the closed position, by fitting the three clamps over the lower and mid screen rails and tightening the wing nuts.

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.