

Bulletin  
Number 5052

Issue 1

Date 5.10.49

Sheet 1 of 1 Sheet

MODELS AFFECTED  
1948-49 LAND-ROVER

UNIT AFFECTED  
**WHEELS**

COMPLAINT

SUBJECT

**TYRE PRESSURES**

THE FOLLOWING INFORMATION SUPERSEDES THAT GIVEN IN SERVICE BULLETIN 5012, THE LAND-ROVER OPERATION MANUAL (EDITIONS A. AND B.) AND THE LAND-ROVER WORKSHOP MANUAL.

The tyre pressures to be maintained on all Land-Rover vehicles (fitted with Avon or Dunlop tyres) are as follows :—

6.00 — 16 tyres

Conditions	Front		Rear	
	Lb./sq. in.	Kgs./cm <sup>2</sup> .	Lb./sq. in.	Kgs./cm <sup>2</sup> .
Normal road use (with load under 550 lb.) (250 Kg.)	20	1,40	26	1,80
Normal road use (with load over 550 lb.) (250 Kg.) in rear)	20	1,40	30	2,10
Cross-country	15	1,05	20	1,40

7.00 — 16 tyres.

Conditions	Front		Rear	
	Lb./sq. in.	Kgs./cm <sup>2</sup> .	Lb./sq. in.	Kgs./cm <sup>2</sup> .
Normal road use (with load under 550 lb.) (250 Kg.)	20	1,40	26	1,80
Normal road use (with load over 550 lb.) (250 Kg.) in rear)	20	1,40	30	2,10
Cross-country	13	0,90	18	1,25

**ACTION TO BE TAKEN.**

In the interests of tyre life, these revised inflation pressures should be brought to the attention of all owners immediately.

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.