

Issue 1

Date 6/3/50

Sheet 1 of 1 Sheet

MODELS AFFECTED

1948-49 LAND-ROVER
(numbered prior to 8667575)

UNIT AFFECTED

BRAKES

BRAKE MODIFICATION

Improved pattern wheel brake units, incorporating one-piece linings, pull-off springs and snail cam adjusters on the leading shoes, have been introduced as from Land-Rover serial number 8667575.

To enable owners of vehicles numbered prior to 8667575 to receive the benefit of the improved design, a complete conversion kit Part No. 234188 is available from our Spares Department at a cost of £1 8s. 2d. The kit comprises all parts necessary to modify one vehicle; full fitting instructions are included.

After modification, leading brake shoes used as subsequent replacement must be of the later type, *i.e.* Part Nos 232071/2.