

Bulletin
Number 5031

Issue 1

Date 1.12.48

Sheet 1 of 1 Sheet

MODELS AFFECTED
LAND-ROVER

UNIT AFFECTED
NUMBERING

COMPLAINT

SUBJECT

LAND-ROVER STATION WAGON SERIAL NUMBERING

INFORMATION IN THIS BULLETIN SHOULD BE MADE AVAILABLE TO EVERYONE CONCERNED, SO THAT OUR SERVICE ORGANISATION MAY WORK TO THE GREATEST DEGREE OF EFFICIENCY.

Standard Land-Rover vehicles produced during the 1949 season will continue in the range of serial numbers 860001 onwards, as detailed in Service Bulletin 5011.

LAND-ROVER STATION WAGON.

Land-Rovers produced with Station Wagon bodies will bear chassis and vehicle numbers in the series 8670001 onwards, with the prefix "R" for a right-hand drive model or "L" for left-hand drive. The serial numbers of units such as the engine, gearbox, etc., will be in the same series (i.e. 860001 onwards) as those for the standard version of the vehicle as described in Service Bulletin 5011.

SERVICE BULLETINS.

The following Service Bulletins will apply to all Land-Rover vehicles produced during the 1948 and 1949 seasons, instead of merely to 1948 models as indicated at the head of each sheet :—

Nos. 5011, 5012, 5013, 5014, 5019, 5023, 5025, 5026, 5027, 5029 and 5030.

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.