

Bulletin
Number 5038

Issue 1

Date 11.2.49

Sheet 1 of 1 Sheet

MODELS AFFECTED

LAND-ROVER

UNIT AFFECTED

NUMBERING

COMPLAINT

SUBJECT

LAND-ROVER AND UNIT NUMBERS

INFORMATION ADDITIONAL TO THAT CONTAINED IN SERVICE BULLETINS 5011 and 5031

After vehicle number 863000, the system of serial numbering for STANDARD Land-Rovers is altered to conform with that used for the Station Wagon version.

A third identification digit (6) is added, so that the 3001st standard vehicle bears the serial number 8663001 and so on, i.e.

Standard Land-Rover serial numbers are 860001 to 863000 and
8663001 onwards.

Station Wagon Land-Rover serial numbers continue as 8670001 onwards.

This alteration applies only to the standard vehicle and chassis numbers.

Serial numbers of units (engine, gearbox, axles, etc.) continue in the series 860001 onwards for both standard and station wagon versions of the vehicle.

LAND-ROVER WITH WELDING OUTFIT

Land-Rovers produced with welding outfits will bear chassis and vehicle numbers in the series 8680001 onwards, with the prefix "R" for a right-hand drive model or "L" for left-hand drive. The serial numbers of units such as the engine, gearbox, etc., will be in the same series (i.e. 860001 onwards) as those for the standard version of the vehicle as described in Service Bulletin 5011.

This sheet replaces that already in your file which bears the SAME bulletin and sheet numbers, but of a LOWER issue number. The old copy should be removed and destroyed.